
| City of Baltimore Wet<br>Smoke and Dyed   | Page 1 of 1                           |  |
|---|---------------------------------------|--|
| Sewershed: Gwynns Falls Company: Savin    |                                       | Date: 9/30/2009                              |
| Test to be performed:  Smoke Dyed Water X | Ground Condition:  Dry ✓ Damp ☐ Wet ☐ | Supervisor: <u>JAW</u>                       |
| Manhole_ID: S08K 004MH                    | Test ID: <u>D1032-006005</u>          | Notification Made: NA (Residents, Fire, 311) |

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



| Defect Loc  | Obs_ClockFrom | Obs_ClockTo | Observation          | Obs_Remarks          |
|-------------|---------------|-------------|----------------------|----------------------|
| 0           |               |             | Start of Survey      |                      |
| 0           |               |             | Manhole              | S08K012MH            |
| 0           |               |             | Water Level          |                      |
| 70.19999695 |               |             | Dye Test Not Visible |                      |
| 70.40000153 |               |             | Abandoned Survey     | DYE TEST IS COMPLETE |